

**DAKSHIN HARYANA BIJLI VITRAN NIGAM**

**Instruction No. 24/MON/2007**

From

The DGM/Monitoring,  
DHBVN, Hisar

To

All CGMs (OP)/GMs(OP)DGMs /AGMs (OP)/  
JEs-I, Incharge in DHBVN.

Memo No:-Ch- /MON-260 Dated:-

**Subject: Providing MCCB on Distribution Transformers as protection to avoid damage.**

It was observed that the number of distribution transformers being damaged under DHBVN is on higher side. The proper investigation for the causes of damage is not being done with this a great loss of revenue is caused to the Nigam, as well as the interruption of supply to the consumers occurs. However, the Instruction for 70% loading of distribution transformers in Rural/Urban areas were issued by the Nigam vide Instruction No 4/MON/2006 dated 13.9.06 as a protection to save the installed distribution transformers from their damage due to over loading. The status of loading of distribution transformers under rural/urban areas have been reviewed and decided that the maximum load allowed to distribution transformers under Urban area shall be 90% and in rural area it shall remain as such i.e. 70% as earlier.

It has been further decided by the Nigam to provide additional protection i.e. MCCB on all the installed distribution transformers so as to avoid/minimize damage of distribution transformers as per detail given below:

1. All the existing distribution transformers in Urban areas shall be provided with "MCCB" as a protection. The work shall be completed by 31.3.2007 positively.
2. With regard to other areas the MCCB on all the installed distribution transformers shall be ensured/provided by 30.9.2007 positively.

It is requested to direct the field officers/officials under your kind control to comply with the above instructions meticulously, failing which disciplinary action will be installed against them. It shall be ensured that the above work/job is completed within the time frame fixed above.

This issues with the approval of MD, DHBVN, Hisar

**DGM/Monitoring,  
DHBVN, Hisar**