

## Damage Rate

(1) The position of transformers damaged during 09/2019 is given as under:-

Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding warranty period	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	15842	86	15	101	0.54%	0.64%
Palwal	16710	111	114	225	0.66%	1.35%
Gurugram-1	17057	63	37	100	0.37%	0.59%
Gurugram-2	11648	41	32	73	0.35%	0.63%
Narnaul	21094	144	68	212	0.68%	1.01%
Rewari	21688	131	87	218	0.60%	1.01%
Bhiwani	42398	188	140	328	0.44%	0.77%
Hisar	25005	92	55	147	0.37%	0.59%
Fatehabad	38863	170	45	215	0.44%	0.55%
Sirsa	48736	264	106	370	0.54%	0.76%
Jind	33886	201	109	310	0.59%	0.91%
<b>DHBVN</b>	<b>292927</b>	<b>1491</b>	<b>808</b>	<b>2299</b>	<b>0.51%</b>	<b>0.78%</b>

(2) The position of transformers damaged during 09/2018 is given as

Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding warranty period	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	15156	77	31	108	0.51%	0.71%
Palwal	16254	88	128	216	0.54%	1.33%
Gurugram-1	16073	54	35	89	0.34%	0.55%
Gurugram-2	10423	50	30	80	0.48%	0.77%
Narnaul	20729	100	83	183	0.48%	0.88%
Rewari	21087	89	58	147	0.42%	0.70%
Bhiwani	41473	203	132	335	0.49%	0.81%
Hisar	21990	92	75	167	0.42%	0.76%
Fatehabad	34550	171	69	240	0.49%	0.69%
Sirsa	44792	224	79	303	0.50%	0.68%
Jind	32995	166	166	332	0.50%	1.01%
<b>DHBVN</b>	<b>275522</b>	<b>1314</b>	<b>886</b>	<b>2200</b>	<b>0.48%</b>	<b>0.80%</b>

## Damage Rate

(3) The Cumulative position of transformers damaged for the year 2019-20 (upto 09/2019) is given as under:

Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding warranty period	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	15842	600	91	<b>691</b>	3.79%	4.36%
Palwal	16710	708	582	<b>1290</b>	4.24%	7.72%
Gurugram-1	17057	367	188	<b>555</b>	2.15%	3.25%
Gurugram-2	11648	227	215	<b>442</b>	1.95%	3.79%
Narnaul	21094	665	461	<b>1126</b>	3.15%	5.34%
Rewari	21688	703	384	<b>1087</b>	3.24%	5.01%
Bhiwani	42398	1189	798	<b>1987</b>	2.80%	4.69%
Hisar	25005	776	478	<b>1254</b>	3.10%	5.01%
Fatehabad	38863	1353	395	<b>1748</b>	3.48%	4.50%
Sirsa	48736	1938	633	<b>2571</b>	3.98%	5.28%
Jind	33886	1506	967	<b>2473</b>	4.44%	7.30%
<b>DHBVN</b>	<b>292927</b>	<b>10032</b>	<b>5192</b>	<b>15224</b>	<b>3.42%</b>	<b>5.20%</b>

(4) The Cumulative position of transformers damaged for the year 2018-19 (upto 09/2018) is given as under:

Name of Circle	No. of Transformer installed	Transformers Damaged			% Damage rate excluding warranty period	% Damage rate including warranty period
		Out of Warranty Period	Within warranty period	Total		
Faridabad	15156	582	180	762	3.84%	5.03%
Palwal	16254	767	783	1550	4.72%	9.54%
Gurugram-1	16073	358	177	535	2.23%	3.33%
Gurugram-2	10423	374	201	575	3.59%	5.52%
Narnaul	20729	812	569	1381	3.92%	6.66%
Rewari	21087	600	442	1042	2.85%	4.94%
Bhiwani	41473	1359	818	2177	3.28%	5.25%
Hisar	21990	764	543	1307	3.47%	5.94%
Fatehabad	34550	1385	507	1892	4.01%	5.48%
Sirsa	44792	1623	586	2209	3.62%	4.93%
Jind	32995	1594	1296	2890	4.83%	8.76%
<b>DHBVN</b>	<b>275522</b>	<b>10218</b>	<b>6102</b>	<b>16320</b>	<b>3.71%</b>	<b>5.92%</b>